

2020 OPERATIONS CALENDAR (Subject to change)

AP26				AP27							AP28		
JANUARY	FEBRUARY	MARCH	APRIL	MAY	JUNE	JULY	AUGUST	SEPTEMBER	OCTOBER	NOVEMBER	DECEMBER		
W	1			1									
T	2			2									
F	3			3									
S	4			4									
S	5	1		5									
M	6	2		6									
T	7	3		7									
W	8	4		8									
T	9	5		9									
F	10	6		10									
S	11	7		11									
S	12	8		12									
M	13	9		13									
T	14	10		14									
W	15	11		15									
T	16	12		16									
F	17	13		17									
S	18	14		18									
S	19	15		19									
M	20	16		20									
T	21	17		21									
W	22	18		22									
T	23	19		23									
F	24	20		24									
S	25	21		25									
S	26	22		26									
M	27	23		27									
T	28	24		28									
W	29	25		29									
T	30	26		30									
F	31	27											
S		28											
S		29											
M		30											
T		31											
W													
T													

- Start up/Machine Development (MD)
- User Mode (UM)
- User Mode (Special Beam Conditions)
- Shutdown - start 0900hrs on the first day, finish 1700hrs on the last day
- Public/company holiday
- Weekend
- Run 2 - Contingency (Shutdown or Machine physics) - Starts 1600hrs on Friday, finish 1100hrs on Tuesday
- Run 3 - Contingency (Shutdown or Machine physics) - Starts 1600hrs on Friday, finish 0900hrs on Monday
- Run 4 & 5 - Contingency (Shutdown or Machine physics) - Starts 0900hrs on Saturday, finish 0900hrs on Monday
- SB_Hybrid User mode (Single Bunch Hybrid)
- FF_Hybrid User Mode (Flat Fill Hybrid)
- Beamline Start-up